


EstuaryWatch Mouth Condition Data Sheet

Completed by: Judith and Don


Site assessed for hazards



Location: Erskine Mouth State (open, perched, closed): Open Date: 20/10/19 Time: 13.50

Water Levels and Tides

Flow:	Time	# of photos
Present? (Y/N)	<u>Y</u>	<u>3</u>
Direction? (in/out)	<u>Out</u>	<u>3</u>
Photopoint site:		
<u>EP1</u>	<u>14.05</u>	<u>3</u>
<u>EP2</u>	<u>14.10</u>	<u>3</u>
<u>EP4</u>	<u>14.15</u>	<u>4</u>



Water Level:	Start	Finish
Height (m)	<u>.87</u>	<u>.86</u>
Time	<u>13.150</u>	<u>14.30</u>

Tidal influence? (- if known; Y/N) N

Tidal range	Time	Height (m)
High	<u>4.35</u>	<u>2.51</u>
Low	<u>10.25</u>	<u>0.93</u>

Physical Condition

	Current	Mode (ie, over the last 2 weeks)
Wind direction	<u>W</u>	
Beaufort Scale No	<u>5</u>	
Sea state Description	<u>Rough</u>	

Data entered:	Yes / No
Photos uploaded:	Yes / No
Data sheet uploaded:	Yes / No
Data entered by:	
Observation ID on database:	
Approved by coordinator	Yes / No

Notes
