

Sampled by: *Juliet and Don*

Site assessed for hazards

Estuary: *Eske*


Mouth State (open, perched, closed): *Open*

Date: *23/2/22* Time: *11.40*

Mouth Observation

Flow:		Time	# of photos
Present? (Y/N)	Direction? (in/out)		
<i>Y</i>	<i>Out</i>	<i>11.50</i>	<i>2</i>
		<i>11.55</i>	<i>2</i>
		<i>12.00</i>	<i>3</i>

Berm measurements: (+/- 0.1 m vertical, 0.5m horizontal)



Notes: *Gauge under bridge still so dirty that any depth below 1.5metre is completely covered with slime/dirt.*

Water Levels and Tides

Water Level:	Start	Finish
Height (m)	<i>0.94</i>	<i>0.90</i>
Time	<i>11.40</i>	<i>12.05</i>

Tidal influence? (- if known; Y/N)

Tidal range	Time	Height (m)
High	<i>4.53</i>	<i>2.3m</i>
Low	<i>10.48</i>	<i>0.42m</i>

Physical Condition

Wind direction	Current	Mode (ie. over the last 2 weeks)
<i>SE</i>	<i>SE</i>	
Beaufort Scale No	<i>1</i>	
Sea state Description	<i>Slight</i>	

Data entered:	Yes / No
Photos uploaded:	Yes / No
Data sheet uploaded:	Yes / No
Data entered by:	
Observation ID on database:	
Approved by coordinator	Yes / No